



STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-97 To (mo./yr.) 12-31-97
2. DOGM File Number (Mine No): M /015 /041
3. Mine Name: DKG Quarry
4. Mineral(s) Mined (or permitted to mine): Gypsum
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
NE 1/4, SW 1/4, NW 1/4, Section 29, Township 22S, Range 9E
1/4, 1/4, 1/4, Section , Township , Range
1/4, 1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Diamond K Gypsum, Inc./Phillip Palmer
8. Permanent Street Address: 1600 S. Red Hills Dr., P.O. Box 35
City, State, Zip: Richfield, UT 84701
Phone: 435-896-8870
9. Company Representative (or designated operator):
Name: Phillip Palmer
Title: Pres.
Business Address: 1600 South Red Hills Dr.
City, State, Zip: Richfield, UT 84701
Phone: 435-896-8870
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 17209
3. If inactive, what year was the mine last active? _____

3. How much **additional acreage** was disturbed during the past year? None
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
No new acreage distrubed

5. How much acreage was **reclaimed** during the past year? 4 acres
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
Covered old deposit with top soil. Structured the area
to control erosion. Seeded and planted elymus elymoides,
hymenoides, and muhlen bergia pungens. Growth is becoming
visable. There is no evidence of erosion.

7. What is the **total disturbed acreage** at years end? 4 acres
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mine existing deposit which should be ample for 1998.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):	<u>Phillip Palmer</u>
Title of Operator:	<u>President</u>
Signature of Operator:	<u>Phillip Palmer</u>
Date:	<u>1-28-98</u>